




**DART**

DESIGN <i>JB</i>	DRAWN BY <i>JB</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA		
CHECKED <i>RF</i>	APPROVED <i>AS</i>	DRAWING NO. D3393	REV. A	SHEET 1 OF 3
DATE 05.02.08		TITLE BATTERY LOCK	SCALE 1:1	
A	05.02.08	NEW ISSUE		

**RELEASED**  
*AS/03/09**AS/03/09*

POSITION FACE **C** OF D3369-5  
PARALLEL TO FACES **D** AND **E**  
AS SHOWN



### D3393-041 BATTERY LOCK ASSEMBLY

#### NOTES:


- 1) WELD PER DART QSI 004
- 2) POSSIBLE SUPPLIER: McMaster-Carr, P/N 9567K21

**COPYRIGHT © 2005 BY DART AEROSPACE LTD.**

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

**DART**

DESIGN <i>13</i>	DRAWN BY <i>13</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>RF</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D3393	REV. A SHEET 2 OF 3
DATE 05.02.09		TITLE BATTERY LOCK	SCALE 1:1

**D3393-1 CASING****NOTES:**


- 1) MATERIAL: 6061-T6/T651 (QQ-A-200/8 OR QQ-A-225/8)  
(REF. DART SPEC. M6061T6B)
- 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1  
POWDER COAT FIRE RED (4.3.5.10) PER DART QSI 005 4.3
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) BREAK ALL SHARP EDGES 0.005 TO 0.010

**COPYRIGHT © 2005 BY DART AEROSPACE LTD.**

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

**DART**

DESIGN 13	DRAWN BY 13	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED RF	APPROVED MS	DRAWING NO. D3393	REV. A SHEET 3 OF 3
DATE 05.02.09		TITLE BATTERY LOCK	SCALE 2:1



### D3393-3 CAM LOCK SHAFT

#### NOTES:

- 1) MATERIAL: AISI 303 S.S. (REF. DART SPEC. M303R0.375)
- 2) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 3) ALL DIMENSIONS ARE IN INCHES
- 4) BREAK ALL SHARP EDGES 0.005 TO 0.010